

REINHOLD ENVIRONMENTAL®



2025 Reinhold/PCUG Round Table Presentation

Hosted by AEP and Buckeye Power

in The Hilton Columbus Polaris Hotel, Columbus, OH

on June 23-24, 2025


All presentations posted on this website are copyrighted by **REINHOLD ENVIRONMENTAL®** (RE). Any unauthorized attempts to print, to download, to modify, to incorporate into other presentations, to link to other websites or to obtain copies for any other uses than the training of attendees to RE Conferences is expressly prohibited unless approved in writing by RE or the original presenter. RE does not assume any liability for the accuracy or contents of any materials in this library which were presented and/or created by persons who were not employees or subcontractors of RE.



PJFF Troubleshooting and Lessons Learned

Emily Yadon, LG&E Mill Creek Station

Mill Creek Station




PJFF Performance: Why It's Important

- EPA regulations
 - High Differential Pressure System Impacts
 - Air compressor strain
-




Environmental Considerations

- Current PM compliance limit: 0.010 lb/MMBTU
- 93% of coal units not slated to retire are able to meet this limit
- PJFFs can help capture SAM and Hg emissions through HL and PAC coatings on bags



High Differential Pressure Concerns

- ID fan load index trip potential
- Higher aux power usage
- Ash agglomeration causing plugging in ash removal systems
- Leak through causing high PM and/or impacts to FGD performance



PJFF Air Compressor Health			
	Hrs Loaded	Air Dewpoint (Deg F)	Dis. Press.
1A	0.00	4.18	90.50
1B	4.24	-33.60	
2A	7.77	-19.70	90.39
2B	2.77	-45.64	
3A	24.00	-114.17	98.73
3B	23.74	-56.72	
4A	24.00	-102.55	99.41
4B	24.00	-103.10	

AQCS Air Compressor Health		
	Hrs Loaded	Dis. Press.
1	23.90	90.59
2	24.00	
3A	15.59	99.79
4B	24.00	

Air Compressor Health

- Daily reports:
 - Hours loaded
 - Dewpoints
 - Discharge pressures
- Leaks in pulse air headers
- Keep dewpoints below -60 deg F




Daily PJFF Report


6/13/2025

	Avg Load	Pulse Rate	Differential Pressure		Clean Air Press (psi)
	(MW)		Max.	Min.	
MC1	-0.01	0	-1.64	-2.96	0.0
MC2	259	14	8.65	2.23	50.2
MC3A	362	4	6.65	1.85	30.6
MC3B		3	7.26	2.43	32.3
MC4A	442	8	7.28	3.57	35.9
MC4B		13	7.74	3.81	33.1


of Cleaning Cycles



Maximum DP




Minimum DP



Pulse Air Headers



- Ineffective cleaning of bags through:
 - Pluggage from flue gas
 - Hose issues
 - Inadequate air pressure
 - Any moisture in air
 - Diaphragm condition



Pulse Jet Valve 76MR Technical Drawing




3.2 Arrangement Drawings



Goyen Valve Top Components

- Valve Body
- Diaphragm
- Solenoid







6/9/2023 12:44:06 PM

2.27 hours

- 2-1 PJFF DIFF PRESS
- 2-2 PJFF DIFF PRESS
- ◆ 2-3 PJFF DIFF PRESS
- ◇ 2-4 PJFF DIFF PRESS
- 2-5 PJFF DIFF PRESS
- 2-6 PJFF DIFF PRESS
- ▲ 2-7 PJFF DIFF PRESS
- △ 2-8 PJFF DIFF PRESS
- + 2-9 PJFF DIFF PRESS
- 2-10 PJFF DIFF PRESS
- × 2-11 PJFF DIFF PRESS
- ⊕ 2-12 PJFF DIFF PRESS
- 2 CLEAN AIR REG PRESS

Pulse Air Headers

- Multiple actions taken:
 - Installing an insert- unsuccessful
 - Replacing valves one at a time
 - Added actuators to tanks
 - Replaced valve seats
 - Replaced check valves
 - Added insulation
- Entire header replacement from OEM is costly (new valves and header): \$36k per header





Replaced check valves with 0.062" pressure washer nozzle orifices





Pulse Air Headers

- Hoses have collapsed and failed due to vacuum
-





Pulse Pipe Build-up

- Have had to clean due to buildup
 - Checking during sampling or changeouts is essential
-



Pulse Pipe Holes

- Ensure holes have not elongated
- Circular hole pattern



Moisture Issues

- Holes in ductwork or other process areas lead to moisture issues
 - Will also cause increased air flow to PJFF
 - Process upsets can cause issues
 - Operating temps above 300 deg F
-



Unit 1 High Differential Pressure Issues

Changed bags March 2021

Unit 1 online (3/25/21 - 6/3/21)

Unit 1 offline (6/3/21 - 7/24/21)

DP started to creep up


ID fan load index alarms by November 2021




Unit 1 High Differential Pressure Issues

- Started Investigating:
 - Were bags introduced to moisture in any way?
 - Not precoated correctly?
 - Abnormal operating temps?
 - Was pulse air working correctly?
 - Air-in leakage/more gas flow?
 - Combustion/Air heater
 - Verified specs/quality of new bags with supplier and third-party testing
-

MC1 PJFF 2021






6/1/2021 12:00:00 AM 6/17/2021 5:41:52 PM 61.00 days 8/1/2021 12:00:00 AM

- 1 PJFF OUT TEMP
- 1 PJFF INL TEMP
- ◆ SELECTED MW INPUT
- BOILER VENT TEMP
- × MC2 SELECTED MW INPUT
- * 1B ID FAN DISCH DUCT TEMP
- 1-1 PJFF HOPPER TEMP
- 1BB ID FAN INLET DUCT TEMP
- 1AB ID FAN INLET DUCT TEMP

- MillCreek.U1.1AQ1_1_OUT_TMP.DACA.PV 308.69
- MillCreek.U1.1AQ1_1_INLT_TMP.DACA.PV 307.79
- ◆ MillCreek.U1.1G3000.DACA.PV 201.28
- MillCreek.U1.1AQ1_0TIBA100.DACA.PV 85.311
- MillCreek.U2.2VNT1D41.DEVCTLA.PV
- MillCreek.U1.1VNT1D41.DEVCTLA.PV
- ▲ Millcreek.U2.2POSBA01Y.DACA.PV
- △ MillCreek.U1.1AQ1_1AIFANC.DEVCTLC.PV
- + MillCreek.U1.1AQ1_1BIFANC.DEVCTLC.PV
- MillCreek.U1.1AQ1_1PDIFF401.DACA.PV
- × Millcreek.U2.2G3000.DACA.PV -0.01282
- * MillCreek.U1.1AQ1_1TIBA018.DACA.PV 312.82
- MillCreek.U1.1ISD1D41.DEVCTLA.PV
- MillCreek.U1.1AQ1_1A_BYPDMPR.DEVCTLA.PV
- ◆ MillCreek.U1.1AQ1_11A_OTLTDM.DEVCTLA.PV
- MillCreek.U1.1AQ1_1PIBA001.DACA.PV
- MillCreek.U1.1AQ1_AIF_DSCHMN.DACA.PV
- MillCreek.U1.1AQ1_AIF_DSCHMN.DACB.PV
- ▲ MillCreek.U1.1AQ1_AIF_DSCHMN.DACC.PV
- △ MillCreek.U1.1AQ1_AIF_DSCHMN.DACD.PV
- + MillCreek.U1.1AQ1_110_HPR_HTR.DEVCTLA.OP
- MillCreek.U1.1AQ1_1TIFF361.DACA.PV 292.13
- × MillCreek.U1.1FP2C28.DACA.PV
- MillCreek.U1.1FP2C29.DACA.PV
- MillCreek.U1.1AQ1_1TIBA017.DACA.PV 304.42
- MillCreek.U1.1AQ1_1TIBA007.DACA.PV 304.93
- ◆ MillCreek.U2.2AQ1_2PIBA018.DACA.PV

- 140.95
- 108.61
- ◆ -0.01440
- 96.821
- × 328.17
- * 233.64
- 160.98
- 202.94
- 172.53



6/15/2021 7:37:42 AM

12.43 days

6/27/2021 5:55:00 PM

- 1 PJFF OUT TEMP
- 1 PJFF INL TEMP
- ◆ SELECTED MW INPUT
- BOILER VENT TEMP
- × MC2 SELECTED MW INPUT
- * 1B ID FAN DISCH DUCT TEMP
- 1-1 PJFF HOPPER TEMP
- 1BB ID FAN INLET DUCT TEMP
- 1AB ID FAN INLET DUCT TEMP



Root cause: leaking FGD isolation damper

- Flue gas leakage
- Permeability and bag performance impacts



**APPEARANCE OF THE NON-COLLECTION
SIDE (BOTTOM DISC)**



**APPEARANCE OF RUST PARTICLES IN BAG
BOTTOM (NON-COLLECTION SIDE)**

**TABLE 1
SUMMARY OF FABRIC TEST RESULTS**

<u>ETS I.D.</u>	<u>BAG I.D.</u>	<u>PERMEABILITY – FPM</u>				<u>MULLEN BURST</u>	<u>TENSILE</u>			<u>MIT FLEX # FLEXES</u>		<u>FABRIC WEIGHT OZ/YD²</u>			<u>FABRIC/ DUST pH</u>
		<u>AS REC'D</u>	<u>AFTER 10" VAC</u>	<u>AFTER 30" VAC</u>	<u>AFTER WASH</u>		<u>PSI</u>	<u>WARP</u>	<u>FILL</u>	<u>WARP</u>	<u>FILL</u>	<u>AS REC'D</u>	<u>AFTER 30" VAC</u>	<u>AFTER WASH</u>	
29529CB % Retention	New Bag #1	7.1 113	- -	- -	- -	1200 100	356 62	502 82	10000 100	10000 100	23.4 102	- -	- -	- -	
29530CB % Retention	Brand New Bag #2	6.3 101	- -	- -	- -	1200 100	492 85	581 95	10000 100	10000 100	22.1 96	- -	- -	- -	
29531DB % Retention	MC1-11-4-N16	3.8 61	4.4 70	5.5 88	- -	983 82	441 76	523 86	10000 100	10000 100	- -	23.3 102	- -	- -	
29532DB % Retention	MC1-7-9-C10	3.8 61	4.0 64	5.0 79	- -	1057 88	464 80	577 95	10000 100	10000 100	- -	24.1 105	- -	- -	
29533DB % Retention	MC1-12-2-L8	4.3 69	4.7 74	5.4 86	- -	995 83	385 67	544 89	10000 100	10000 100	- -	23.4 102	- -	- -	
29534DB % Retention	MC1-6-15-D19	4.0 64	5.1 81	6.6 105	- -	1050 88	407 71	620 102	10000 100	9277 93	- -	23.8 104	- -	- -	
29535DB % Retention	MC1-2-22-D6	2.8 45	4.0 63	4.1 66	5.9 93	815 68	311 54	462 76	7674 77	5446 54	37.8 165	25.4 111	23.6 103	2.65 -	
29536DB % Retention	MC1-1-24-P22	3.8 61	4.8 76	4.9 77	6.1 97	955 80	405 70	547 90	9774 98	8964 90	29.7 130	24.3 106	23.8 104	2.81 -	
<i>New Fabric Values[^]</i>	<i>N/A</i>	6.3	-	-		1197	577	610	10000+	10000+		22.9			

%Retention = (Old Value/New Value)*100

[^]Average new fabric values taken from the QA/QC Program under ETS Report 20-4128-L dated January 6, 2021, and are included for % retention calculations.

Preventative Measures

- Ensure PJFF dampers were all shut on outages
- Monitor seal air system closely on FGD isolation damper
- Alarm if PJFF temperatures exceed 100 deg F while unit is offline




Making Bags Last Until Retirement

- Have used high energy cleaning:
 - Not a permanent fix
 - Can lower DPs to limp until retirement or changeout
 - Could damage bag membrane
 - Can cost about \$13-15/bag
 - Cheaper than a changeout
-



MC1 PJFF 2022



Compartment Lids

- Gasket:
 - Helps seal up doors
 - Prevents air-in leakage
 - Have swapped to square gasket
 - More costly up front, but holds up over time
 - Bolts for doors
 - Heat causing them to loosen
 - Bolts have bent over time
 - Have replaced some of the bolts
-



Bypass Dampers

- Poppet Inspections:
 - Open and check poppets are attached
 - Have had several bypass poppets fail:
 - Fixed in house with welders




Outlet Poppets

- Ensure proper opening and closing of poppets from the compartments
 - Failures would result in higher DPs



Leak Tests

- Important after changeouts
- Helps ensure PJFF will meet PM limits
- Identifies failed bags effectively



Location	Weight Analysis (% Increase)	Permeability (4.0 cfm)	Mullen Burst Strength (800 psi)	Warp Tensile Strength (350 lbf)	Fill Tensile Strength (350 lbf)
-E10	7%	3.95	1000	396	550
7-J6	8%	5.06	1000	442	574
0-D6	4%	4.1	1000	463	636
-D19	8%	4.06	1000	474	745
K10	6%	4.59	1000	459	692
G18	7%	4.15	1000	463	676
-E10	8%	5.42	1000	401	649
7-J6	7%	4.24	1000	446	801
0-D6	14%	5.33	1000	431	679
-D19	6%	5.16	1000	392	685
K10	7%	4.44	1000	426	674
G18	8%	4.84	1000	379	625
-P16	3%	5.28	1000	396	550
4-E7	5%	5.19	1000	442	574
-D3	5%	5.35	1000	463	636
D18	3%	5.06	1000	474	745
-E5	8%	7.28	1000	459	692
-M15	6%	5.6	1000	463	676
6-A6	18%	5.59	1000	396	550
4-E7	14%	4.94	897	396	550
-D3	14%	4.73	867	463	636
D18	12%	4.98	1000	474	745
55	18%	4.65	1000	459	692

Bag Sampling

- Bag life predictability:
 - Prevents early or late changeouts
 - Trend over time
- Determines if there are issues:
 - Moisture
 - Flow inequities
 - Cage movement
 - Cage wear




Maintaining ESPs for PJFF Performance

Less ash going
to the PJFF

Less cleaning
cycles

Improved bag
life

Less
changeouts



Maintaining ESPs for Flyash Beneficial Reuse

- Flyash captured in the ESP contains lower SO₃ concentrations
 - Captured ESP ash at Mill Creek is sellable
 - Profits go towards benefitting LG&E customers
 - Beneficial reuse as concrete additive
 - Approx. 25k tons of Mill Creek flyash was used to construct the bridges in Louisville
 - PJFF ash goes to the landfill
 - Costly to landfill
 - Reduces landfill lifespan
-





Questions/Discussion

