

REINHOLD ENVIRONMENTAL®



2025 Reinhold/PCUG Round Table Presentation

Hosted by AEP and Buckeye Power

in The Hilton Columbus Polaris Hotel, Columbus, OH

on June 23-24, 2025

All presentations posted on this website are copyrighted by **REINHOLD ENVIRONMENTAL®** (RE). Any unauthorized attempts to print, to download, to modify, to incorporate into other presentations, to link to other websites or to obtain copies for any other uses than the training of attendees to RE Conferences is expressly prohibited unless approved in writing by RE or the original presenter. RE does not assume any liability for the accuracy or contents of any materials in this library which were presented and/or created by persons who were not employees or subcontractors of RE.



SCR & LPA Screen Efficiency

APS Four Corners Case Study

*Written and Presented By:
Jessica Hernandez - APS Sr. Environmental
Engineer
Andrew Kline - IGS Director of Technical Sales*





Overview

- Operational Background and Overview
- Diagnosing the Problem
 - LPA Screen Plugging
 - Air Cannon Failures at SCR
 - SCR Performance
- IGS Corrective Actions and Implementation
- Results to Date
- Conclusion



SCR Added and
began Operating:
March 2018

Expected Shutdown:
2031




Operation Unit 4 & 5:
750 MW Each


General Arrangement APS Four Corners



LPA System at Four Corners



SCR System at Four Corners



Operational Background


- Normal Operation 2018-2019
 - System Back Pressure Reached 12 in H₂O
- Spring 2019 – Screw Conveyor at LPA Screens taken out of service due to continued maintenance issues
 - System Back Pressure Reached 20 in H₂O
 - Booster Fans started to max out, MW's Lost
 - LPA Screen Back Pressure started to reach 3 in H₂O
 - Increased Flue Gas Velocities Caused Premature LPA Screen Erosion


Operational Background

- Spring 2020 (U5), 2021 (U4) – 3 Layer SCR increased to 4 Layers
 - Corrosion in Air Preheater
 - System Back Pressure Reached 20 in H₂O Faster
 - Booster Fans continued to max out, MW's Lost
- July 2022 - Jessica Hernandez joined APS
 - Worked with Bruce Salisbury and Coy Cody to understand system challenges and history

Operational Background

- Spring 2023 – Reduced SCR to 3 Layers
 - Improvements achieved at SCR and Preheater
- Spring 2025 – New LPA Screen, New LPA Air Cannons, New SCR Air Cannons, improvements to Preheater
 - System Back Pressure expected to stay below 14 in H₂O
 - LPA Screen Back Pressure expected to stay under 1 in H₂O
 - Booster Fans continued to operate optimally






LPA Screen Operational Issues

- Screw Conveyor was inoperable due to continued maintenance issues
- Ash Piled at Screw Conveyor Blocking >50% of the screen
- LPA at Four Corners exhibited characteristics of slag and ash LPA types with a porous, sintered matrix surrounded by fly ash agglomerates.
 - I.E Very Erosive
- Reduced LPA Screen surface area due to plugging




LPA Screen Operational Issues




LPA Screen Operational Issues

- Ash Piling Increased velocities through the screen, significantly decreasing screen life
 - Holes developed – they were incorrectly repaired or not repaired
 - LPA broke through to SCR, Preheater, Baghouse, etc.
- Rappers were ineffective in clearing screen due to flow disruptions



LPA Screen Operational Issues



SCR Air Cannon Operational Issues

- Four Corners has a positive pressure system
 - Ash back flowed into Air Cannons
- Air Cannons Corroded
 - MI NDA determined end of life of Air Cannons would be 2028
 - Maintaining system required inspection on all 64 pressure Vessels and replacing pressure reliefs per ASME Code
- Thermal Safety Shields (Gate Valves) Failed causing Safety Issues
 - Sch. 40 Pipe was threaded, creating a thin area. Corrosion caused failure
 - Air Cannons were shooting off the unit – MAJOR safety concern.

SCR Air Cannon Operational Issues



Corrosion from Positive Pressure System

SCR Air Cannon Operational Issues




Corrosion from Positive Pressure System

SCR Performance Issues

- Ash Piles on all layers of the catalyst
 - Unit 5 had a maintenance event where steam penetrated the SCR causing significant issues. Unit 4 is not as severe.
- Air Cannons and Sonic Horns were plugged and not operating
- SCR Catalyst Screens damaged from narrowed Air Cannon shots.
- LPA breakthrough visible on all layers. Reducing the life of the SCR from 5-7 years per layer to 3-5 years.

SCR Performance Issues



SCR Performance Issues



Unit 4 1st Layer Plugging

SCR Performance Issues



Unit 4 2nd Layer Plugging

SCR Performance Issues



Unit 5 1st Layer Plugging

SCR Performance Issues




Unit 5 2nd Layer Plugging

SCR Performance Issues



LPA Breakthrough




Plugged Sonic Horn

SCR Performance Issues



LPA Underside of Unit 5 SCR – Steam Event



SCR Screen Failure

SCR Performance Issues



Unit 5 – Uneven Corrosion

SCR Performance Issues



Unit 4 – Uneven Corrosion

Other System Issues

- LPA Breakthrough also impacted the duct, baghouse, and preheater
- Operating 3 Layers vs. 4 Layers reduces SO_3 by 25%, or an expected 228 Tons per year
 - Operational issues progressed further after 4th layer installed
 - Higher SO_3 concentration raises the Acid Dew Point(ADP), causing sulfuric acid damage to downstream equipment.
 - Acid condensation produces “sticky” surfaces resulting in ash accumulation, specifically in the preheater

IGS Solutions - LPA Screen

- LPA Screens Completely Replaced
- Upgraded Two-Stage Coating to Allow for Easy Inspection
- LPA Screen Air Cannons Installed to Replace Rappers




IGS Solutions - LPA Screen

- APS decided to install vacuum ports in lieu of replacing/repairing the Screw Conveyor
- Air cannon cleaning system will help keep ash fluidized, helping to reduce ash piling
- APS and IGS decided to add a large cannon nozzle in the hopper to break Ash Bridging to improve vacuum effectiveness
- Air cannon monitoring system installed




IGS Solutions - LPA Screen



LPA Screen Maintenance is Critical – Yet Often Overlooked!

LPA SCREENS ARE LIKE BRAKE PADS, YOU NEED TO CHANGE THEM BEFORE THEY FAIL!!!



- *Early Signs of Failure, Plan for Change!*



Failure Imminent, Change Now!



Severe Failure

Regular Qualified Inspection is Critical to Protect the SCR Between Outages

Two-Stage Coating Makes Insection Quick and Easy!



IGS Solutions - SCR Air Cannon Upgrades

- Air Cannon Upgraded from 4" to 8" increasing power
- Nozzles Upgraded from 4" to 6" increasing blast coverage and depth




IGS Solutions - SCR Air Cannon Upgrades

- Multiplier Design - Reduced the ASME Pressure Vessels from 32 per unit to 4 per unit
- Protection from Positive Pressure
 - Multipliers add layer of protection between the process and air cannon internals
 - A vertical discharge section adds distance and elevation preventing corrosive media from reaching multiplier
 - Discharge piping and nozzle material upgraded to stainless



IGS Solutions - SCR Air Cannon Upgrades

- Air Cannon Monitoring System Installed
 - Real time feedback to DCS
 - Reduces need for physical inspection
 - Can Alert DCS of a system malfunction and allow for a quick repair




Before & After - SCP




Results

- Inspections have not been conducted post LPA System upgrade
- Inspections of the SCR show less Ash Piling
- After 140 days of Operation on Unit 5 and 90 days on Unit 4:
 - **30-60% less Pressure Drop through out the full system**
 - Projected to reach 14 in H₂O at most, reduction of 6 in H₂O


Unit 5 North




Unit 5 South



Unit 4 North



Unit 4 South



Results

- Restored Production & Eliminated DeRates
- Reduced ID Fan Loading
- Reduced Maintenance on Booster Fans, Bag House, & SCR
- Reduced Damage to Preheater
- Reduced SCR Layer Replacements Projects by 1 or 2 before end of life.
 - Reducing waste and Capital \$\$ needed

Conclusions

- System Performance & Reliability Improved
- MW Production Restored
- Safety Improved, Maintenance Reduced

Special Thanks to:

- Dracyon – Jeff Shelton and his team for support during the projects
- Ceram – Jared Koliha and his team for Project Assistance
- Environex – Andy Toback and his team for their support in reviewing Catalyst Samples and estimating remaining life
- APS Team Members – Bruce Salisbury (Engineer, Retired), Coy Cody (Engineer, left APS)

Jessica Hernandez, M.S.E

Sr. Environmental Engineer
Jessica.Hernandez@aps.com
480-267-6476



Thank you

www.integratedglobal.com

